

**Sensitive Security Information (SSI)**

No part of this document may be disclosed to persons without a "need to know," as defined in 49 CFR 1520.5.



Ohio Oil Gathering, Bells Run Station

**Security Equipment Maintenance Documentation Form**

Equipment: LOWER FLARE CAMERA	Maintenance Type: CHECK COMMUNICATIONS CAMERA
Maintenance Date: 6-10-17	Work Performed by: JOHN AMOS

Provide a description of the Maintenance Performed: (attach supporting documentation)

CALLED @ MID OHIO VALLEY INTEGRATED SYSTEMS  
FOUND BAD CONNECTION ON WIRING GOING TO PC

Additional Comments:

VIDEO LOSS OF LOWER FLARE CAMERA  
FOUND PROBLEM APPROX. 10 AM WORK PERFORMED AND REPAIRED  
APPROX. 1300 6-10-17

CERTIFYING SIGNATURE:

Security Record Retention Requirements: 2 years USCG/DHS