

Bells Run Facility

ALARM & SHUTDOWN INSPECTION

Device: Flame Arrestor DA- 101

Date of Inspection: 7/27/20

Description: Flame Arrestor DA- 101

Inspected By: J. PRIDER

Location: Dock System

Last Inspection: 8/19

Type of Device & Function: FLAME ARRESTOR

Set Point: N/A.

Testing Frequency: 1 years

Type of Test Performed:

VISUAL INSPECTION
AND CLEANING

Results of Test:
O.K.

Corrective Action Taken, If Applicable:
—

Comments:
DOWN RIVER SIDE NOT USED

Signature: J. Prider

Date: 7/27/20